



- NOTE-
- 1) ALL WELDS SHOULD BE GROUND AND POLISHED SMOOTH TO A #3 (150 GRIT) FINISH.
 - 2) ALL ROUGH EDGES SHOULD BE CLEANED OF ANY BURR'S.
 - 3) ALL ANGLES ARE AT 90° UNLESS OTHERWISE NOTED.
 - 4) ALL RADIUS AND CORNERS ARE TO BE A 1/32 UNLESS OTHERWISE NOTED.

LEGEND

WORKING SPACE (DO NOT BLOCK)

THIS DRAWING AND ANY ATTACHMENTS TO THIS DRAWING ARE CONFIDENTIAL AND PRIVILEGED INFORMATION, AND ARE THE SOLE PROPERTY OF LANCE JACOBS, AND WAGNER PACKAGING MACHINERY, PLANO-TX

REVISIONS			
REV	DESCRIPTION	DATE	BY

APPROVED BY: _____
 DATE: _____
 SIGNATURE: _____

PROJECT	WAGNER PACKAGING MACHINERY
OWNER	2904 DARTMOUTH DR.
PO#	PLANO, TEXAS 75075
SCALE	PHONE: 972-355-8456 FAX: 972-499-1898
DRAWN BY	WWW.WAGNERPKG.ORG LANCE@WAGNERPKG.ORG
CHECKED BY	WAGNER PACKAGING MACHINERY RESERVES PROPRIETARY RIGHTS TO THIS DRAWING AND THE DATA SHOWN THEREON. SAID DRAWING AND DATA ARE PROPRIETARY AND ARE NOT TO BE USED OR REPRODUCED FOR ANY PURPOSE WITHOUT THE WRITTEN CONSENT OF WAGNER PACKAGING MACHINERY.
DATE	SLRRRP / WACO BOTTLING
CHECKED	
REV	Wagner Pkg - LJ PPK DWG SH SIZE D 1000 XMM P2182021 SH 1 REV 0